

TEST REPORT

Page 1/3

3F, Building Block 2, No. 3400 Gonghexin Road, Jing'an District - Shanghai 200436, P.R. CHINA 上海市静安区共和新路3400号2幢3层

Tél.: +86 21 68 55 50 32 Fax: +86 21 68 55 50 33 E-mail: ctcshanghai@ctcgroupe.com

Congmin HUANG / huangcongmin@intco.com

Report No.: S200707328_2

29 July 2020

APPLICANT: SHANDONG INTCO MEDICAL PRODUCTS CO. LTD

(C41221)

NO. 9888 QIWANG ROAD, NAOSHAN

INDUSTRY PARK QINGZHOU SHANDONG

CHINA

Date of receipt :21 July 2020

Testing period

:23 July 2020

:27 July 2020

Buyer: --

Service

SYNMAX VINYL GLOVES Sample description:

Style / Article no. :7S, 8M, 9L, 10XL

Test(s) requested

: REGULAR

Brand / Section

Season

End use Factory name

Factory code

Revision

:Amend sample information

For CE Marking: Yes

Previous report

Product category

Product type

:FIRST TEST Test stage

Supplier name

Exported to

1. Conclusion:

	<u>Tests description</u>	<u>Conformity</u>
	EN ISO 374-1	
1	Air Leak Test	Pass
2	Water Leak Test	Pass

Fail: requirements not met None: no requirement for this test N/A: not applicable Pass: requirements met

Approved by

Henry YAN

Laboratory Manager



TEST REPORT

Page 2/3

Report No.: S200707328_2

29 July 2020

APPLICANT: SHANDONG INTCO MEDICAL PRODUCTS CO. LTD

(C41221)

2. Sample(s) description assigned by laboratory:

Size	Analyzed product	<u>Description</u>	Sample information
	GLOVE		
		Whole glove	



200707328



TEST REPORT

Page 3/3

Report No.: S200707328_2

29 July 2020

APPLICANT: SHANDONG INTCO MEDICAL PRODUCTS CO. LTD

(C41221)

3. GLOVE/

Whole glove

	Method	Client Requirement	Unit	Result	Conformity
▲ 5.2. Air Leak Test	EN 374-2:2019				Pass
Glove thickness			mm	0.09	
Air pressure used to test			kPa	2.5	
Result		No air bubbles		No air bubbles	
▲ 5.2. Water Leak Test	EN 374-2:2019				Pass
Result		No water leak		No water leak	

END OF TEST REPORT

▲: The test was carried out by external accredited laboratory under their accreditation scope.